

Accuway Loadcell TM Cable Handset



OPERATING INSTRUCTIONS


SET-UP Plug the cable into the Loadcell
Plug the other end of the cable into the Handset

ON Press and hold **ON / OFF** for approximately 2 Seconds and release
Display will light-up

WEIGHING Use the appropriate rated shackles and accessories
Take up the slack in the shackles/accessories
Press GROSS/NET Key to Zero the Load Indication
Complete the weighing

INDICATORS Press PEAK at any time to get the last recorded maximum
or peak figure

OFF Press and hold **ON / OFF** for approximately 2 Seconds and
release
Display will power down



SPECIFICATIONS

Power Supply (Loadcell)	2 x AAA Alkaline (1.5v)
Supply Current	35mA (Typical)
Loadcell Battery Life	100 Hours (approx)
Display Range	0.1% Full Scale (Min)
Zero Tempco	0.2µv/°C (Typical)
Accuracy	0.5% Reading
Environmental Sealing	IP65

Power Supply (Handset)	2 x AA Alkaline (1.5v)
Low Battery Condition	<2.4v DC
Display Type	LCD 12.7mm Characters
Battery Life	Up to 450 Hrs in Low Power Mode
Span Tremco	<30ppm/°C
Operating Temperature	-20°C to +60°C
Cable Length	5 Metres (Standard)

